

SHELF TAG SUPPLY

Your #1 Source for Warehouse Signs, Bar Code Labels, Card Holders & Shelf Magnets

Sign Edge Stiffener Assembly Instructions

Assembly instructions for triangular, cube and large flat signs.

Instructions:

Stiffeners are to be placed on the top edge of triangular and cube signs, and the long side (generally 18" inches or longer) of flat signs.

1. Carefully pry open one end of the stiffener and insert the sign edge at one end. Work the stiffener down onto the entire sign edge - Figure A.
2. The stiffener should be nearly flush with the sign corner at both ends and not extend beyond the sign end. If the stiffener needs to be adjusted, remove and re-apply. - Figure B.

Questions? Call 800-851-8980 for assistance.

Figure A





Figure B



Additional Supplies Part Numbers:

Edge Stiffener
QES (per inch)

Hanging Chain
QCH (100')

Adhesive Mounts
QAM (2)

S-Hooks
QSH (25)